


* KETERKENDALIAN dan KETERAMATAN

Controllability and observability

Kendali/PLANT:

Ilustrasi:

masuk



PLANT
(Kendali)

C = controllable
 $\bar{C}$ = uncontrollable
 O = observable
 $\bar{O}$ = unobservable



keluar

- stabilizable
- unstabilizable